

Photo No.:	: 1	Date and Time: April 27, 2021 - 08:20			
Photographer: Clay Weiss				Direction: South	
Latitude:	0		Longitude:	0	
Description: Crew spraying creek banks at midway creek section					



Photo No.: 2 Date and Time: April 27, 2021 -	Date and Time: April 27, 2021 - 08:44			
Photographer: Clay Weiss Direction: North				
Latitude: 0	Longitude:	0		
Description: Surface skimming south creek section north of the pond				





Photo No.:	3	Date and Time: April 27, 2021 - 13:57			
Photographer: Clay Weiss				Direction: Southwest	
Latitude:	0		Longitude:	0	
Description: Surface skimming midway creek					



Photo No.:	4	Date and Time: April 27, 2021 - 16:29		
Photographer: Clay Weiss Direction: North				
Latitude:	0		Longitude:	0
Description: The south creek section north of the pond post surface skimming				

